

INTERFLON RELIABILITY IMPROVEMENT ALERT

Correct Cleaning Method for Interflon Treated Components

OFFICIAL

Endorsement

Author: Alan Wright
Role: Senior Technical Rail Engineer
Organisation: Interflon Rail



Introduction

Incorrect cleaning methods can remove the protective lubrication layer and reduce performance.

Key Message

Do **NOT** use degreasers on any Interflon-treated components.

Why This Matters

Degreasers will remove the MicPol coating, eliminating the protective layer and requiring full reapplication.

Risks

- Loss of lubrication layer
- Increased friction and wear
- Rework and additional maintenance

Best Practice

Use Lube EP or Lube TF to clean and remove contamination. This can be done by spraying the product and cleaning the contamination off with a rag and brush.

Wipe surfaces clean and reapply the correct quantity of lubricant.

Operational Impact

Maintains coating integrity and reduces unnecessary maintenance effort.